


1/10 Hardayal S. GILL HIT1P066/HSJ920030274US1 (LN)





2/10 Hardayal S. GILL HIT1P066/HSJ920030274US1 (LN) **FREE** 210 2C 2C 215 **SPACER** 227 FM_{1} -226 **2**D 2D 220 APC -224 ⊗___223 FM_{2} 222 -230 **AFM** FIG. 2A 200 130 120 115 110,154 ABS - 260 270 272 280 250 FIG. 2B

3/10 Hardayal S. GILL HIT1P066/HSJ920030274US1 (LN)








FIG. 3


4/10 Hardayal S. GILL HIT1P066/HSJ920030274US1 (LN)




5/10 Hardayal S. GILL HIT1P066/HSJ920030274US1 (LN)




6/10 Hardayal S. GILL HIT1P066/HSJ920030274US1 (LN)




7/10 Hardayal S. GILL HIT1P066/HSJ920030274US1 (LN)



8/10 Hardayal S. GILL HIT1P066/HSJ920030274US1 (LN)



9/10 Hardayal S. GILL HIT1P066/HSJ920030274US1 (LN)



10/10 Hardayal S. GILL HIT1P066/HSJ920030274US1 (LN)

